BOUCHARD B120 RELEASE SHORELINE SEGMENT SUMMARY



5 Lan Drive, Suite 200 Westford, Massachusetts 01886 Tel. (978) 692-1114 Fax (978) 692-1115

GeoInsight Project Number 3871-002

SEGMENT IDENTIFICATION: W1C-01

SEGMENT NAME: Butler's Point

SEGMENT LOCATION: Marion, Massachusetts (Map attached)

MAXIMUM DEGREE OF INITIAL OILING: Moderate (Oiling Score: 3.00)

SEGMENT INSPECTION STATUS: Did not pass IRAC inspection on 07/28/2003, further treatment feasible. Passed MCP IRA Inspection on 11/19/2003.

SITE-SPECIFIC INFORMATION

PHYSICAL CHARACTERISTICS:

Primary Shoreline Type/ Geology:

• 1D: Rip rap seawalls, bulkheads, piers, docks, and pilings.

Secondary Shoreline Type/ Geology:

• 1C: Mixed sand and gravel beaches (pebble to boulder) and rip rap groins (jetties).

Hydrogeology:

 Sippican Harbor is located to the northwest, Sedge Cove to the north, and Buzzards Bay to the southeast.

Bedrock Geology:

 Bedrock underlying this segment is identified as undivided granite, gneiss, and schist (Zen, 1983).

ENVIRONMENTAL SENSITIVE RECEPTORS (Identified within 500 feet of segment):

Aquifer: None at segment.

Protected Open Space: At segment.

<u>Public Ground Water Supply Wells</u>: None at segment. <u>Public Surface Water Supply Wells</u>: None at segment.

Areas of Critical Environmental Concern (ACEC): None at segment.

Vernal Pools: None at segment.

<u>Priority Habitats of Rare Species</u>: Adjacent to segment: Buzzards Bay aquatic environment. <u>Estimated Habitats of Rare Wildlife</u>: Adjacent to segment: Buzzards Bay aquatic environment.

Floodplains: At segment: 100-year floodplain.

HUMAN SENSITIVE RECEPTORS (Identified within 500 feet of segment):

<u>Segment Use</u>: Private and semi-public coastline. Residential dwellings are located within 500 feet of the segment. The segment is accessible via roadway.

Frequency of Use: Presumed to be seasonal and year round residential use.

SUMMARY OF INSPECTION ACTIVITIES

WRF INSPECTIONS

(Wildlife Field Reconnaissance- Shoreline or On-Water Observations; Bird Transect Study.)

WRF inspections pertaining to this segment were not conducted.

NRDA FIELD ACTIVITIES SUMMARY

(Natural Resource Damage Assessment)

Note: Includes Shoreline Cleanup Assessment Team (SCAT) inspections and activities. SCAT forms were completed by field inspection teams working under the direction of Unified Command.

DATE	SUMMARY OF INFORMATION RECORDED BY INSPECTION TEAM
05/21/2003	Tarballs, tar patties, and oil residue observed in the middle intertidal zone primarily along jetties,
	and one area of oil was observed on residence stairs. The surface oil coverage was estimated to
	be 1% to 10%.
06/03/2003	Light to moderate oiling on cobbles, boulders, and gravel areas (where oil was observed up to a
	maximum depth of 2 inches deep). Sporadic tar patties (2 to 6 inches in diameter) were
	observed on cobble areas and along wrack line. Oil was noted to be distributed from lower tidal
	to upper tidal zone, with the heaviest areas having no greater than 10% cover. Cleanup crew
	was at segment during the inspection.

IRAC INSPECTIONS

(Unified Command Immediate Resp onse Action Completion inspections and activities.)

DATE	SUMMARY OF INFORMATION RECORDED BY INSPECTION TEAM
07/28/2003	Light to moderate oiling on cobbles, boulders, and gravel areas (where oil was observed up to a
	maximum depth of 2 inches deep). Segment did not meet IRAC criteria endpoints and further
	treatment was feasible.

MCP FIELD ACTIVITIES SUMMARY

(Massachusetts Contingency Plan inspections and activities under the direction of the Licensed Site Professional-of-Record.)

DATE	SUMMARY OF INFORMATION RECORDED BY INSPECTION TEAM
11/19/2003	Site reconnaissance: Areas of trace splatter scoured to a stain were observed.
04/13/2004	Site reconnaissance: Trace sporadic splatter (approximately 2 to 4 inches in diameter) was observed on the seawall. Minor amount of residual oil (up to approximately 6 inches in diameter) was observed in between jetty boulders.
08/25/2004	Site reconnaissance: Evidence of oil was not observed.
06/22/2005	Shoreline inspection to check for salt marshes: Salt marsh not present.


Note: GeoInsight did not receive IRA citizen calls pertaining to this segment.






W1C-01 Butler's Point Bouchard B No. 120 Oil Spill Buzzards Bay, MA


NATURAL HERITAGE AND ENDANGERED SPECIES MAP



2IE PRIORITY RESOURCE MAP



TOPOGRAPHIC MAP



LAC

AS SHOWN

JKB

LEGEND

NHESP 2005 MA PRIORITY
HABITATS FOR STATE-PROTECTED
RARE SPECIES

NHESP 2005 MA ESTIMATED HABITATS OF RARE WILDLIFE





KDT

01/25/06 387IWIC-01

MJW

3871-002

PROJECT #:

WIC-01

