

Figure 10. Initial Oiling Conditions May 3, 2003 Bouchard B No. 120 Oil Spill Buzzards Bay, MA







Figure 9. Initial Oiling Conditions May 2, 2003 Bouchard B No. 120 Oil Spill Buzzards Bay, MA






Figure 8. Initial Oiling Conditions May 1, 2003 Bouchard B No. 120 Oil Spill Buzzards Bay, MA







Figure 7. Initial Oiling Conditions April 30, 2003 Bouchard B No. 120 Oil Spill Buzzards Bay, MA



- ENTRIX Water Samples (Sheen/product observed)ENTRIX Water Samples
- (No sheen/product observed)
  Pockets of Tarballs,
  tar patties, sheen, &/or slicks
- 4/28/03 Onshore/Nearshore Oiling
  - 4/29/03 Onshore/Nearshore Oiling

Figure 6. Initial Oiling Conditions April 29, 2003 Bouchard B No. 120 Oil Spill Buzzards Bay, MA






Figure 5. Initial Oiling Conditions April 28, 2003 Bouchard B No. 120 Oil Spill Buzzards Bay, MA








Figure 4. Initial Oiling Conditions April 27, 2003

Bouchard B No. 120 Oil Spill Buzzards Bay, MA










Figure 11. Initial Oiling Conditions May 4, 2003 Bouchard B No. 120 Oil Spill Buzzards Bay, MA